


END  
500xNP

**Figure 1 (010, Biopsy Device)**



**Fig 1a**

Figure 1a (010, Biopsy Device)

16




Figure 2 (100, Needle Assembly)







FIGURE 2A



# Figure 3 (200, Piston and Cutter Assembly)



# Figure 4 (300, Front End Cap Assembly)



**Figure 4a (302, Journal Assembly)**




Fig 4s




Fig 4c

Fig 4d

# Figure 5 (400, Cylinder and Spool Valve Assembly)





Figure 5c, 400, Spool Valve Assembly

5c







Figure 6 (500, Rear End Cap Assembly)






Figure 7

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☒ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**